

Site Photographs



Photograph 15: Sewer grate for public water supply along railroad.



Photograph 16: Former dry-cleaning building.



Photograph 17: Equipment in former dry-cleaning building.



Photograph 18: Empty suspended AST in former dry-cleaning building.

Site Photographs



Photograph 19: Pipe below suspended AST.



Photograph 20: Drainage features in former dry-cleaning building.



Photograph 21: Office space.




Photograph 22: Office space


Site Photographs



Photograph 23: Electrical in former dry-cleaning building.



Photograph 24: Water and gas hookup in former dry-cleaning building.



Photograph 25: Bathroom.



Photograph 26: Rear room in former dry-cleaning building.

Site Photographs



Photograph 27: Rear room in former dry-cleaning building.



Photograph 28: Rear of former dry-cleaning building.



Photograph 29: View looking north from former dry-cleaning building.



Photograph 30: Office and boiler room building.



Photograph 31: Foundation remnants of former cement block garage.



Photograph 32: Entryway easement to Kraft property.

Site Photographs



Photograph 33: Office.



Photograph 34: Boiler room building (left), office (right)



Photograph 35: Inside of office building.



Photograph 36: Inside of boiler room building.

Site Photographs



Photograph 37: Vent pipe and fill pipe for UST outside boiler room building.



Photograph 38: Fill pipe for UST outside boiler room building.



Photograph 39: Trench and old materials for concrete manufacturing.



Photograph 40: Concrete trench.

Site Photographs



Photograph 41: Equipment on Dahlstrom property.



Photograph 42: Equipment on Dahlstrom property looking west towards Webco.



Photograph 43: Old concrete manufacturing storage area.



Photograph 44: Scrap pile looking west towards Webco site.



Photograph 45: Stained soils, looking west towards Webco site.



Photograph 46: View from railroad looking northeast onto Dahlstrom property.

Site Photographs



Photograph 47: Three 55-gallon drums with stained soils.



Photograph 48: Scrap pile.



Photograph 49: Scrap, drum, and scale.



Photograph 50: Dahlstrom office building and scrap.



Photograph 51: Dahlstrom garage and scrap.



Photograph 52: Empty drums and homemade smelter.

Site Photographs



Photograph 53: Scrap and buckets between Dahlstrom office and Dahlstrom garage.



Photograph 54: Scrap alongside of Dahlstrom garage.



Photograph 55: Old equipment, scrap, drums.



Photograph 56: Gas tank in scrap pile.



Photograph 57: Old cars and scrap yard equipment.



Photograph 58: Scrap yard equipment.

Site Photographs



Photograph 59: Fuel tanks, tires, scrap.




Photograph 60: Scrap yard equipment.



Photograph 61: Scrap yard equipment.



Photograph 62: Metal shavings in barrel on Dahlstrom property.



Photograph 63: Electrical transformers located on Dahlstrom property.



Photograph 64: Scrap pile below electrical transformers..

Site Photographs



Photograph 65: Scrap pile and old UST.



Photograph 66: Stained soils around scrap yard equipment.



Photograph 67: Buckets catching fluids under scrap yard equipment.



Photograph 68: Buckets catching fluid under scrap yard equipment and stained soils.

Site Photographs



Photograph 69: Scrap piles and disturbed earth along northern boundary of subject site.



Photograph 70: 55-gallon drum in scrap pile.



Photograph 71: Lid to water valve for public water supply.



Photograph 72: Valve for public water supply.

Site Photographs



Photograph 73: Unknown pipe exiting bank on east side of Kraft property.



Photograph 74: Drain in center of subject site.



Photograph 75: Stained soils on Kraft and Dahlstrom property.



Photograph 76: Stained soils on Kraft and Dahlstrom property.

Site Photographs



Photograph 77: Stained soils on Kraft property.



Photograph 78: Stained soils on Kraft property.



Photograph 79: Stained soils on Kraft property.



Photograph 80: Stained soils on Kraft property looking east towards office and boiler room building.

Site Photographs



Photograph 81: Debris inside Dahlstrom office.



Photograph 82: Debris inside Dahlstrom office.



Photograph 83: Debris inside Dahlstrom office.



Photograph 84: Debris inside Dahlstrom office.

Site Photographs



Photograph 85: Entrance to Dahlstrom garage.



Photograph 86: Debris and scrap in Dahlstrom garage.



Photograph 87: Debris and scrap in Dahlstrom garage.



Photograph 88: Debris and scrap in Dahlstrom garage.

Site Photographs



Photograph 89: Debris and scrap in Dahlstrom garage.



Photograph 90: Debris and scrap in Dahlstrom garage.



Photograph 91: Homemade smelter in Dahlstrom garage.



Photograph 92: Empty buckets and scrap in Dahlstrom garage.

Site Photographs



Photograph 93: Homemade smelter and burnt waste.



Photograph 94: Burnt waste on ground from homemade smelter.



Photograph 95: Burnt waste on ground from homemade smelter.



Photograph 96: Exhaust pipe on rear of Dahlstrom garage from homemade smelter.

Site Photographs



Photograph 97: TENORM pipe sections.



Photograph 98: Homemade smelter.



Photograph 99: Scrap in yard.



Photograph 100: Split old UST.

Site Photographs



Photograph 101: Staining around scrap yard equipment.



Photograph 102: Staining around scrap yard equipment.



Photograph 103: Staining on Dahlstrom property.



Photograph 104: Staining on Kraft property.

Site Photographs



Photograph 105: Staining on Kraft property.



Photograph 106: Staining on Kraft property.

DRAFT

DRAFT

APPENDIX B



Document Information

Document Number: ENV-MAN-GBUR-0001	Revision: 03
Document Title: Quality Manual	
Department(s): Quality	

Date Information

Effective Date: 02 Jan 2020

Notes

Document Notes:

All Dates and Times are listed in: Central Time Zone

Signature Manifest

Document Number: ENV-MAN-GBUR-0001**Revision:** 03**Title:** Quality Manual

All dates and times are in Central Time Zone.

ENV-MAN-GBUR-0001

QM Approval

Name/Signature	Title	Date	Meaning/Reason
Nasreen Derubeis (009976)	Quality Manager II	02 Jan 2020, 03:45:16 PM	Approved

Management Approval

Name/Signature	Title	Date	Meaning/Reason
Jesse Woodring (003204)	Safety Coordinator	30 Dec 2019, 09:58:09 AM	Approved
Richard Kinney (005816)	Manager - Lab Operations	30 Dec 2019, 10:02:47 AM	Approved
Brayan Hampton (007472)	Manager - Lab Services	30 Dec 2019, 10:36:25 AM	Approved
Thomas Sylvester Jr. (006012)	Regional Systems Manager	30 Dec 2019, 12:28:02 PM	Approved
Kelli Dabler (007645)	Service Center Manager	30 Dec 2019, 01:22:45 PM	Approved
Danette Cavalier (007656)	Manager - Lab Services	30 Dec 2019, 02:27:19 PM	Approved
William Billings (004488)	General Manager	31 Dec 2019, 07:07:59 AM	Approved
Colin Walters (005945)	Senior General Manager	31 Dec 2019, 11:04:16 AM	Approved
Rachel Christner (005630)	Project Manager II	02 Jan 2020, 02:35:09 PM	Approved
Nasreen Derubeis (009976)	Quality Manager II	02 Jan 2020, 03:45:40 PM	Approved



LABORATORY QUALITY MANUAL
Pace Analytical Services, LLC

COPYRIGHT © 2019 Pace Analytical Services, LLC.

TITLE PAGE

LABORATORY QUALITY MANUAL

Prepared for:

Pace Analytical Services, LLC
1638 Roseytown Road
Suites 2, 3 & 4
Greensburg, PA 15601
Phone: 724-850-5600

Pace Analytical Services, LLC
Mechanicsburg Service Center
5020 Ritter Road, Suite 102
Mechanicsburg, PA 17055
Phone: 609-389-5468

Pace Analytical Services, LLC
Shamokin Service Center
6521B State Route 61
Shamokin, PA 17872
Phone: 570-648-2216

Pace Analytical Services, LLC
Somerset Service Center
12 World's Fair Drive, Suite L
Somerset, NJ 08873
Phone: 732-652-6452

DRAFT